

K I N G



DT2022064-V2

[kingliving.com](http://kingliving.com)

Reo II


# Reo II

## Reo II

Headrest : Gas Strut Operation  
 Arm Options : STD or SMART Pocket


### STD

Side : Headrest Down



### SMART Pocket


Side : Headrest Up




### Armchair



### 2 Seater



### 2.5 Seater



### 3 Seater




## Reo II Recliner

Headrest & Footrest : TouchGlide Technology  
 Arm Options : STD or SMART Pocket


### STD

Side : Headrest Down




### SMART Pocket

Side : Headrest Up




Side : Reclined




### Armchair Recliner




### 2 Seater Recliner



### 2.5 Seater Recliner




### 3 Seater Recliner




## Ottoman


Front



Top



## Optional SMART Pocket Accessories



Effective June 2022. Reo II Recliners use TouchGlide® Technology. The weight limit for the recliner mechanism used in Reo II Recliners is 120kg (264.5lb). The weight limit for Reo II Recliner footrest is 15kg (33lb). Reo II Recliners have support legs (Reo II Armchair Recliner excepted). King has a policy of continuous improvement, changes to products and specifications may be made without prior notice. Images and drawings are representative of design only. Accessories not included.


**IMPORTANT: ALWAYS FULLY RETRACT THE FOOTREST BEFORE SITTING IN OR GETTING OUT OF THE RECLINER.** To avoid damage to your recliner, the reclining function should only be operated when you are seated in the recliner. Open footrests have a 15kg (33lb) weight limit and must be closed before getting out of, or getting into the seat. Sliding over an open footrest to get out of the seat, or get into a fully reclined seat may cause damage to the recliner mechanism and can result in the sofa tipping forward in extreme cases. This built-in tipping point was specifically designed to preserve the integrity of the mechanism if too much pressure is placed on it, and to avoid permanent damage. Damage caused by improper use of recliners will not be covered under Warranty.

# Reo II Packages


## Packages : Reo II

Arm Options: STD or SMART Pocket


### Armchair




### 2STR



### 2.5STR




### 3STR




## Packages : Reo II Recliner (R Recliner : F Fixed)

Arm Options: STD or SMART Pocket


### Armchair R




### 2STR RR




### 2.5STR RR



### 3STR RFR



### 3STR RRR




## Stitching Detail : Reo II

Rear : Headrest Down


### Armchair




### 2 Seater



### 2.5 Seater



### 3 Seater




## Stitching Detail : Reo II Recliner

Rear : Headrest Down


### Armchair Recliner




### 2 Seater Recliner



### 2.5 Seater Recliner



### 3 Seater Recliner



Effective June 2022, Reo II Recliners use TouchGlide® Technology. The weight limit for the recliner mechanism used in Reo II Recliners is 120kg (264.5lb). The weight limit for Reo II Recliner footrest is 15kg (33lb). Reo II Recliners have support legs (Reo II Armchair Recliner excepted). King has a policy of continuous improvement, changes to products and specifications may be made without prior notice. Images and drawings are representative of design only. Accessories not included.

**IMPORTANT: ALWAYS FULLY RETRACT THE FOOTREST BEFORE SITTING IN OR GETTING OUT OF THE RECLINER.** To avoid damage to your recliner, the reclining function should only be operated when you are seated in the recliner. Open footrests have a 15kg (33lb) weight limit and must be closed before getting out of, or getting into the seat. Sliding over an open footrest to get out of the seat, or get into a fully reclined seat may cause damage to the recliner mechanism and can result in the sofa tipping forward in extreme cases. This built-in tipping point was specifically designed to preserve the integrity of the mechanism if too much pressure is placed on it, and to avoid permanent damage. Damage caused by improper use of recliners will not be covered under Warranty.

